

# RELEASE NOTES: BE367/FE210 Firmware 1.30

SES-20170801-A



## Product Release Information: BE367/FE210 Firmware 1.30

<b>Product</b>	BE367/FE210
<b>Version Number</b>	1.30
<b>Firmware Release Date(s)</b>	March 6, 2017
<b>Production Release Date</b>	April, 2017
<b>Customer Support</b>	For more information or support, visit our website.

### Attention:

This document contains the **Release Notes** for BE367/FE210 Firmware Release 1.30 and includes feature updates made since the previous production Firmware Release 1.28 on June 8, 2015

### Installation and Update Notes:

Allegion recommends keeping all devices up to date with the latest firmware and software. We strive to provide the best products and service for our customers.

Our latest firmware and software releases will allow the customer to get the most from their devices.

#### ***Installation***

Refer to the “Legacy Device Firmware Update” Section of the SUS User Guide – Appendix B for full details. You can find the latest SUS User Guide [here](#).

#### ***Who should update?***

Specifically, all customers who would be interested in the following Recent Changes should update:

### Recent Changes:

- Fixed: Daylight Saving Time (DST) issues
  - Audit added for DST adjustments
  - DST check added for Vendor Access Management credentials
  - DST check added for expired user credential

Revision	Comments	Date	Author
SES-20170801-A	Initial release	8-2-2017	RS