



---

**Product Release Information: AD-Series Firmware AD.A.143**

|                              |   |
|------------------------------|---|
| <b>Product</b>               | AD-Series   |
| <b>Version Number</b>        | Firmware Package: AD.A.143  |
| <b>Firmware Release Date</b> | January 2024  |
| <b>Customer Support</b>      | For more information or support, visit our document <a href="#">library</a> . |

**Attention:**

This document contains the **Release Notes** for AD-Series Firmware Package AD.A.143. This update includes updates and improvements made after the AD.A.141 firmware package released in April 2022.

**Installation and Update Notes:**

***Installation***

Refer to the “Device Firmware Update” Section of the SUS User Guide – Appendix B for full details. You can find the latest SUS User Guide [here](#), and the Android SUS User Guide [here](#). Additional Quick Start information is found at the Support Library [here](#) by searching for “SUS Quick Start”.

***Who should update?***

Allegion recommends keeping all devices up to date with the latest firmware and software. We strive to provide the best products and service for our customers.

Our latest firmware and software releases will allow the customer to get the most from their devices.

Specifically, all customers who would be interested in the following New Feature and Recent Change should update:



**New Features:**

- **SiK2: Support added for Apple HID NFC and Android HID NFC**
    - Support added to read the credential on Android and iOS Devices
    - Requires a configuration card to Enable
- NOTE:** This feature is only available on SiK2 Readers manufactured after 12/23 with “**Uses HID p/n SEL55100000**” on the label.

**Recent Changes:**

- **SiK2 Readers: Updated UI for HID Configuration Cards**
  - New response for presenting a Configuration Card that is already set
    - A fast beep is sounded after presentation
  - Success and Failure UI's remain the same

**Version Compatibility:**

The AD.A.143 Package contains the following individual product firmware versions:

**NOTE:** All Devices that have been updated in the AD.A.143 release are listed in **bold** in the table below:

| <b>Devices</b>      | <b>Firmware Version</b> |
|---------------------|-------------------------|
| <b>AD-200</b>       | <b>2.53.0</b>           |
| <b>AD-250</b>       | <b>2.52.0</b>           |
| <b>AD-300</b>       | <b>2.53.0</b>           |
| <b>AD-302</b>       | <b>2.5.0</b>            |
| <b>AD-400</b>       | <b>2.53.0</b>           |
| <b>AD-402</b>       | <b>2.5.0</b>            |
| KP-PR-SM-MT         | 2.48.0                  |
| <b>KP-PR-SM-MT2</b> | <b>2.11.3</b>           |
| MG                  | 2.44.0                  |
| PIB300-2D           | 2.19.1                  |
| PIM400-485-RSI      | 2.31.0                  |
| PIM400-485-VBB      | 2.31.0                  |
| PIM400-TD2          | 2.26.0                  |
| WPR400              | 2.32.0                  |
| WRI400              | 2.9.2                   |
| <b>CT5000</b>       | <b>2.9.0</b>            |